SAS Superstructure 04-SF-80-13.2 / 13.9

Run Date: 11/8/13 11:27 AM

BLUE TAG ISSUES (SAS Job Site-OBG)

Filter ((Cat='Major Issues' OR Cat='Second-Tier Issues' OR Cat='Quality Management Issues') AND Location like '%shanghai%' AND (status='Pending' OR status='Briefing' OR status='Resolved' OR status='Void')) Issue No Date Initiated WBS Location Initiated By **Proposed Resolution/Status Construction Response Design Response** Cost/Credit Material SMR # Status Summary Major Issues During the QA Paint samples test, the batch Part A: Changxing Island, Void 28-Jan-11 LM8944PV and Part B:LM3019CH failed the gloss Shanghai, P.R. labortary test. The failure paints have been applied on the following components. Steel Barriers: W5-SB1-089 P.P77.5-78, E2-SB2-008 P.P99-99.5, W5-SB1-107 P.P98-98.5, W5-SB1-111P.P97-97.5, W5-SB1-101P.P185.5-86, E2-SB1-020P.P106.5-107, W5-SB20-082P P106-106 5 W5-SB1-085P.P78.5-79, W5-SB1D-016 P.P88.5-89, W5-SB21-1 P.P108-108.5, W5-SB1-108P.P99.5-100, W5-SB1-089 P.P85-85.5, W5-SB1D-007P.P91.5-92, W5-SB1D-013P.P107-107.5, W5-SB29A-001 P.P100.5-101, E2-SB1-058P.P89.5-90, E5-SB1B-081P.P107.5-108, W5-SB1-014 P.P83-83.5, E2 -SB1-43 P.P103.5-104, W5-SB13A-004P.P80.5-81, W5-SB1-054 P.P104-104.5, E2-SB10-050 P.P100.5-1001 W5-SB2-014 P.P78-78.5, E5-SB2D-001 P.P108-108.5, W5-SB28-007P.P104.5-105, W5-SB20-002P.P99-99.5, W5-SB1-075 P.P80.-80.5, E2-SB3-002P.P100-100.5, W5-SB2-010P.P103-103.5, W5-SB1-106P.P101.5-102, E2-SB1D-051P.P100.5-101, E2-SB1-048P.P106-106.5, W5-SB1-087P.P103.5-104,E2 -SB1-089P.P85-85.5, E5-SB4-006P.P104-104.5, W3-SB1-046P.P107.5-108, W5-SB28-004P.P105-105.5, W5-SB2-012P.P96-96.5, W5-SB1-081P.P82.5-83, W5-SB1-110P.P102.5-103 W5-SB2-011P.P84-84.5,W5-SB1-083P.P105.5-106, W5-SB1-112P.P96.5-97 W5-SB1-090P.P93-93.5, W5-SB29A-002P.P88-88.5, E5-SB13-008P.P96.5-97 E2-SB1C-012P.P108-108.5, W5-SB2-015P.P101-101.5, W5-SB28A-003 P.P97.5-98 Bikepaths: BK4A-017, BK4A-055, BK4A-019, BK4A-023, BK4A-026, BK4A-030, BK4A-036, BK6A-002, BK4A-018, BK4A-005, Second-Tier Issues Documentation of known punch list items are reported in Documented Repairs and Inspections of items Concurs with METS. N/A Pending 24-Dec-09 Shanghai. Changxing Island, (PRC) the "Combined Voyage 1 Punchlist for Oakland 2009-12listed has commenced in Oakland. Please 30". These items were classified as "Category D" on the reference the "Combined Voyage 1 Punchlist for Master Punchlist. This combined punchlist was Oakland 2009-12-30" for further details. This generated to capture the remaining 55 "Category D" combined punchlist are issued with the state letter 05.03.08-000032. The letter confirms that as of items which were not being completely addressed in China. 12-30-09 (CST) ABF and the Department are in agreement with the items (55 in total) listed on the Combined Voyage 1 Punchlist. 29-Mar-10 Documentation of the thirty six (36) Master Punchlist Changxing Island, Documented repairs and inspections of items S61 Pendina items are reported in the "Combined Voyage 2 Punchlist Shanghai, P.R. listed will commence in Oakland. Please for Oakland 2010-03-29" signed by both the Department China reference the "Combined Voyage 2 Punchlist for and ABFJV. The combined punchlist was generated to Oakland 2010-03-29" for further details. This capture the remaining "Category D" items to be combined punchlist are issued with the state letter completed in Oakland, California 05.03.08-000035. The letter confirms that as of 03-29-10 (CST) that ABF and the Department are in agreement with the items (36 in total) listed on the Voyage 2 Punch list.

